MARYLAND HISTORICAL TRUST

WA-V-179
District 4
Map 7
Parcel 10
MAGI # 2213225935

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

		 			
1	NAME				
	HISTORIC				
Bla	AND/OR COMMON Lirs Valley Lak	:e			
2	LOCATION				
Bla	STREET & NUMBER				
	CITY, TOWN		X VICINITY OF Clear S	CONGRESSIONAL DIST	RICT
Mar	STATE Yland	•		COUNTY Washington	
3	CLASSIFICA	TION	•		1
	CATEGORY DISTRICTBUILDING(S)STRUCTURE X_SITEOBJECT	OWNERSHIP PUBLIC PRIVATE BOTH PUBLIC ACQUISITION IN PROCESS BEING CONSIDERED	STATUS XOCCUPIED —UNOCCUPIED —WORK IN PROGRESS N ACCESSIBLE XYES: RESTRICTED —YES: UNRESTRICTED	PRES AGRICULTURE COMMERCIAL EDUCATIONAL ENTERTAINMENT GOVERNMENT INDUSTRIAL	SENT USE MUSEUMPARKPRIVATE RESIDENCE FRELIGIOUSSCIENTIFICTRANSPORTATION
, =	OWNER OF		_NO	MILITARY	XOTHER:
	STREET & NUMBER	Inland Fish and G	ame Commission	Telephone #:	
	West Preston	Street			
Bal	CITY.TOWN timore		VICINITY OF	STATE , : Maryland	zip code 21201
5	LOCATION COURTHOUSE. REGISTRY OF DEEDS, ET	OF LEGAL DESC Washington Count		Liber #: 435 Folio #: 259	
	STREET & NUMBER	West Washington	Street		
	CITY, TOWN	Hagerstown		STATE Maryland	21740
6	REPRESENT	ATION IN EXIS	TING SURVEYS		
	DATE		EFDE?	STATE	
	DEPOSITORY FOR SURVEY RECORDS		FEDERAL	STATECOUNTYLOCA	L
-	CITY, TOWN			STATE	

7 DESCRIPTION

X_EXCELLENT

__FAIR

CONDITION

__DETERIORATED

__GOOD __RUI

__RUINS __UNEXPOSED **CHECK ONE**

__UNALTERED

CHECK ONE

X_ORIGINAL SITE

__MOVED DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Blairs Valley Lake is a large man made body of water ewned by the Maryland Inland Fish and Game Commission. On the property is a farmstead which includes a house which appears to be brick cased and a frame bank barn. The house is a two story, five bay structure with a double porch separate from the main roof span along the entire front elevation. Its surface is painted red. The house may be a two part structure. All windows have two over two pane sashes which appear to be replacements. The windows are quite small relative wall area. A brick smoke house is located near the house.

Since this house is occupied, its construction could not be examined closely. It still appears likely, however, that the structure is at least in part built of log and cased with brick veneer. Two six over six pane sashes remain at the second story level of the front elevation. The house has an inside end chimney of brick at the west end wall and a small interior brick flue. The roof is covered with corrugated sheet metal.

The brick smoke house located adjacent to the main house has a decorative brick open work ventilator.

South of the house is a frame bank barn resting on fieldstone foundations. It is at present used for storage and for offices for the Blair's Valley Lake.

The house is in deteriorated condition.

SPECIFIC DAT	ES	BUILDER/ARGI			
1400-1499 1500-1599 1600-1699 1700-1799 1800-1899 1900-	ARCHEOLOGY-HISTORIC AGRICULTURE ARCHITECTURE ART COMMERCE COMMUNICATIONS	CONSERVATION ECONOMICS EDUCATION ENGINEERING EXPLORATION/SETTLEMENT INOUSTRY INVENTION	LAW LITERATURE MILITARY MUSIC PHILOSOPHY POLITICS/GOVERNMENT	—RELIGION —SCIENCE —SCULPTURE —SOCIAL/HUMANITARIAN —THEATER —TRANSPORTATION —OTHER (SPECIFY)	
_PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANOSCAPE ARCHITECTURE	RELIGION	
PERIOD	A	REAS OF SIGNIFICANCE C	IECK AND JUSTIFY BELOW		

This house cannot be dated without further study. However, its general form as well as the size and placement of doors and windows could suggest a pre 1850 log building subsequently sheathed with brick.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECES	SSARY
10 GEOGRAPHICAL DATA ACREAGE OF NOMINATED PROPERTY 377.25 acres	
VERBAL BOUNDARY DESCRIPTION .	•
LIST ALL STATES AND COUNTIES FOR PROPERTIES	S OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE	COUNTY
STATE	COUNTY
11 FORM PREPARED BY NAME/TITLE Paula Stoner, Architectural Historian	
ORGANIZATION	DATE
Preservation Associates	July 1978 TELEPHONE
STREET & NUMBER 109 West Main Street, Box 202	301-432-5466
CITY OR TOWN	STATE
Sharpsburg	Maryland 21782

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401

(301) 267-1438

ADDENDA

In 1984 the Department of Natural Resources contracted with Joe Getty to conduct a follow-up survey of selected historic properties on DNR lands. DNR funded the field survey and photography but did not prepare finished copy. The attached photocopy pages were forwarded to the Maryland Historical Trust to supplement existing files. All original material and photographs remain in the possession of the Department of Natural Resources under the supervision of Ross Kimmel (x3771).

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Nam	l e (indicate p	referred name)		
historic				
and/or common	Snyder Farm B	Sarn, Blairs Va	They hake.	
2. Loca				
street & number	Blair's Valley Roa	ed, of mile useth of Hing.	ng Rock Road	not for publication
city, town	Clear Spring	× vicinity of	congressional district	Sixth
state	Maryland	county	Washington	
3. Clas	sification		0	
Category district building(s) structure site object	Cwnership	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresses	
name	Department of	Natural Resonnes		
street & number	Tomes State Of		telephone no).:
city, town	Amapilis	9	and zip code MD	21401
5. Loca		al Description		~(10)
		shington County Court		liber 435
street & number	₩ <u>,</u>	+ Washington Stace	+	folio 259
city, town	1/4	iaus from	state	MD
6. Repr		in Existing	Historical Surve	
itle \mathcal{D}	NR Survey	-		
-,	uly 1178		federalX state	countylocal
lepository for sur		trust of Natural	Pesones	iocai
city, town	Annex	orlis		ND

						_		
_			es					_
7		3 8 4	~	\sim		* a	-	-
•	_		_			3.3	2.33	
		-	\sim		- 2-			-

Survey No. UA - 179

f dition

excellent

good

 $\frac{\varkappa}{}$ fair

__ deteriorated __ ruins Check one unaltered X altered

Check one

∠ original site

_ moved date of move

ruins X altered moved date of unexposed

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

ADDENDUM TO CRIGINAL FORM:

SNYDER FARM BARN

 $\frac{Sp}{ch}$

Pr su

8. Significance					Survey No. W.4-5-179			
Period	⊢1499 ⊢ 1599 ⊢ 1699 ⊢ 1799 ⊢ 1899	archeology-historic agriculture architecture art				g	_ landscape architectur _ law _ literature _ military _ music _ philosophy _ politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates		Buil	der/Arci	nitect			
check:	а	icable Criteria:A nd/or icable Exception:				E	FG	
	Leve	l of Significance: _	_nat	ional	state	1	ocal .	
Prepare		a summary paragraph	of s	ignific	cance an	d a g	general statement	of history and

10. Geographica	l Data		
Acreage of nominated property Quadrangle name UTM References do NOT complete			Quadrangle scale
Zone Easting Northin	ıg	B Zone	Easting Northing
C		D F H	
Verbai boundary description and List all states and counties for p	roperties overla		county boundaries
state	code	county	code
11. Form Prepar	ed By		
name/title Tse Letty			
organization Department of	Vatual Resource	<u>s</u>	date January 1984
street & number Tawes State C	Hire Bldg		telephone 264-3771
city or town Amer pelis	·		state 110

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

DRAFT--DESCRIPTION

SNYDER FARM BARN

Addendum to original form

The Snyder Farm Barn is a frame bank barn on a stone foundation built around the turn of the century. Oral traditions states that the barn replaced an early structure that was destroyed by fire. Most of the materials in the barn are early twentieth century while some of the hardware in the stone foundation may date from the earlier barn. The structure is 50 feet by 76 feet and contains pens on the foundation level for livestock. The main level has a projecting forceast and open framing. The framing system is traditional to the turn of the century and supports a principle purlin roof structure. At one time, the barn was painted in a white and green ornamental pattern that included arched patterns around the door on the south side.

The Snyder Farm Barn is located on the west side of Blairs Valley Road, .4 mile north of Hanging Rock Road. It is located adjoining Blair's Valley Lake, a large man-made body of water owned by the Maryland Inland Fish and Game Commission, north of Clear Spring in Washington County. The barn is located on a gently sloping site near the Snyder Farmhouse.

The Snyder Farm Barn is a frame bank barn on a stone foundation. It is constructed into a bank and has a foundation level with forebay on the north facade. The barn is covered in a vertical barn siding that at one time was painted white with green trim. The north facade ground story contains several

doors which lead to livestock pens. The main story of the north facade contains a large sliding door flanked by single ventilator windows. The south facade is the bank facade and contains sliding doors which had a painted arched ornamentation on them (the western-most door has been painted over a solid color. The east gable end contains a side entrance into the barn and three ventilator windows with a small ventilator window in the gable. There are also two foundation windows on this facade. The west gable end has a fully exposed foundation level covered in vertical siding with an entrance at the southernmost bay and two four pane windows along this level. The main story also has a doorway at the southernmost point, three ventilator windows, and a small ventilator in the gable. The gable roof is covered in sheet metal.

The interior of the foundation level has a large open room in the easternmost section. The westernmost section is divided into pens with a central aisle, an aisle along the south foundation wall, and a section of four pens on the east side and six pens on the west side of the central aisle. The pen arrangement includes hay mangers constructed of rounded dowals running through the stalls. The main floor contains a small partitioned office in the southeast corner of the structure that is now used for Blairs Valley Lake. The remainder of the main floor is open to the ceiling and contains framing system with bracing to support two principle parlins that carry the common rafter through. The framing is mortised, tenned, and pegged.


The exterior of the barn is covered in a vertical siding. Most of the hardware in the barn is early twentieth century.

There are two dates painted at separate locations around the barn. At the northwest corner painted in green letters on a concrete covered stone foundation are the words "Henry Snyder, 1921." On one of the doors are the letters "C A S, Apr. 1, 1917." Oral traditions states that an early barn was destroyed by fire on this site and current barn was built by Henry Snyder in the early twentieth century.

Significance.

The Snyder Farm Barn is a representative frame bank-barn from the turn of the century. In construction techniques, materials, and use, the structure displayed characteristics typical of those found for such agriculture buildings in central Maryland.


Oral tradition states that the structure was built in the early twentieth century on the foundation of an earlier barn that was destroyed by fire. In one corner of the foundation are the painted words Henry Snyder 1921 painted in green paint over concrete applied to the stone foundation. Over one door under the fore are the initials C.A.S. with the date Apr. 1, 1917. These do not necessarily indicate date of construction (they could indicate date of painting or other improvements). It appears that these dates could be accurate for construction of the barn based on examination of the hardware and construction techniques.





WA- I- 179 Snyder Fain Barn


Foundation Level

scale - 1/8" = 1 foot










1A-V-179 Snyder Farm Barn top- South facade unter- Forebay botton- Forebay detail WA-V-179

WA-V-179 Snydu Faim Bain top. interior framing center- framing detail bottom - livestock pen

WA-II-179 Snyder Farm Barn top - west facade - detail center - "Herry Snyder 1921" 60 Hom - "CAS APR 1, 1977"


WA-I-179 Snyder Fam Born Blaves Valley Road top- Strap hinge button- iron latch





WA-V-179 Incliain Springs WMA "Snyder Farm, N.W. View Dec. 1978

Poula Stoner
Preservation Associates



Indian Springs Lutdlife Manag. Area Snyder Farm - Ban S. W. View

Dec. 1973

WA-V- 179

Preservation Associates

Paula Stoner